

## 10<sup>th</sup> DELPHI Dismantling Meeting


Monday, 12 Feb 2001, 8:15 h

Progress during week 06/2001

Planning for week 07/2001

A.O.B

## Progress during last week (week 6/2001)



## Planning for this week (week 7/2001)



		11 Feb '01							18 Feb '01	
ID	Task Nam e	S	М	T	W	T	F	S	S	М
1	transport B1 -> point 2									
2	Inspection securite CISSCT									
3	remove MUF side C									
4	transport 8 chambers to Peney									
5	remove HOF side C								:	
6	transport HOF counters to B									
7	dismantle vac. pumps									
8	dismantle turret side C									
9	empty endcap aureole							]		
10	undress Barrel							]		